

Einzelwerte:	1. 3.82	6. 3.71	11. 3.83	16. 3.83	21. 3.83	26. 3.75	31. 3.68	36. 3.84	41. 3.84	46. 3.87	51. 3.80	56. 3.85	61. 3.78	66. 3.80	71. 3.79	76. 3.74	81. 3.80	86. 3.72	91. 3.75	96. 3.86
	2. 3.82	7. 3.76	12. 3.79	17. 3.78	22. 3.81	27. 3.80	32. 3.78	37. 3.74	42. 3.77	47. 3.71	52. 3.77	57. 3.78	62. 3.73	67. 3.82	72. 3.81	77. 3.78	82. 3.79	87. 3.85	92. 3.77	97. 3.88
	3. 3.86	8. 3.82	13. 3.74	18. 3.85	23. 3.89	28. 3.77	33. 3.74	38. 3.76	43. 3.63	48. 3.79	53. 3.87	58. 3.79	63. 3.72	68. 3.75	73. 3.80	78. 3.86	83. 3.80	88. 3.89	93. 3.91	98. 3.90
	4. 3.76	9. 3.81	14. 3.78	19. 3.86	24. 3.85	29. 3.74	34. 3.76	39. 3.89	44. 3.81	49. 3.84	54. 3.86	59. 3.93	64. 3.80	69. 3.80	74. 3.72	79. 3.91	84. 3.76	89. 3.88	94. 3.84	99. 3.81
	5. 3.75	10. 3.74	15. 3.87	20. 3.87	25. 3.71	30. 3.68	35. 3.68	40. 3.78	45. 3.83	50. 3.75	55. 3.84	60. 3.84	65. 3.75	70. 3.83	75. 3.71	80. 3.75	85. 3.73	90. 3.84	95. 3.83	100. 3.81


Kurvengrafik

Drehmoment

3.84

Freq.

2000



Grenzfreq. 300 Hz

msec: 277.222, Nm: 2.10

Zoom

Restore

Laden

Sichern

Filter

Drucken

Ende

Kurvengrafik

Drehmoment


3.84

Winkel

643

Freq.

2000



Grenzfreq. 300 Hz

°: 595.126, Nm: 2.10

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Sichern

Filter

Drucken

Ende